Balancing in HighTech Precision



Easy balancing at turning lathes

Uneven running, low speeds and poor surfaces caused by eccentric, unbalanced workpieces?



MPM balancing ring with balancing segments: 3.WRS.xxx

No problem with MPM balancing rings!

For unbalance compensation just move the balancing segments or move them to the angle positions shown in the BMT150M display.



Complete balancing electronics with sensors: 3.BMT150M